

BUILDING SAFETY CERTIFICATE

No. 6574

Dated:- 22/09/2026

Certified that the existing building - Dr.Kalmadi Shamarao High School, Survey No- 147/8+9+10 and Survey No- 147/1+4+6 ,Park Marina Road, Prathmesh Park, Mouje Baner Tal- Haveli, Pune- 411045. is having block (s)/ Floor(s) as per details below.

Detail Block(s) in School	Block (2)
No. of Floor(s) in the Block	Basement + Ground Floor +Stilt 4 Floors

The building is owned/occupied by Kannada Sangh, Pune have complied with the Building Safety requirement as per rules verified by the officers concerned of Public Works Department Pune on 17/09/2026 in the presence of B. R. Mankar, Liaison Officer,Address- Dr. Kalmadi Shamarao High School, Survey No- 147/8+9+10 and Survey No- 147/1+4+6, Park Marina Road, Prathmesh Park, Mouje Baner Tal- Haveli, Pune- 411045. and that the building is structurally safe and fit for occupancy for running school with effect from 17/09/2026 for a period of One year in accordance with rule and subject to compliance of the specific conditions as appended.


Nil

Issued on/ 22/09/2026 at Pune by


(N.M. Payal)
Deputy Engineer,
P. W. Rajbhavan Sub Division
Pune-411007.



'Countersigned'


(P. S. Khairmode)
Executive Engineer,
Public Works Division,
Pune-411001.

OW.No./ DB / NOC / 6574 / 2026
Office of the Executive Engineer,
Pune Public Works Division, Pune-01.

Date- 12 2 SEP 2026

Copy to:- 1. Deputy Enginner, P.W. Rajbhavan subdivision, Pune.
2. Principal, Dr. Kalmadi Shamarao High School, Survey No. 147/8+9+10 and 147/1+4+6, Park Marina Road, Prathamesh Park, near Jupiter Hospital, Baner, Taluka-Haveli, District-Pune (For information Vide your letter Ref.No. 236/2026 Date- 31/08/2026)