



Sunil Mutualik & Associates

Structural Consultants

1349/50, Shukrawar Peth, Arthshilp, 3rd Fl, Bajirao Rd, Above Hotel Ganaraj, Pune : 2

Ph : 020 - 2447 6705, 2446 7302, 2449 7294, 2448 8712

E – mail : sunil.mutalik@gmail.com

Ref. No.: BSC-KSE-2401-26

Building Safety Certificate.

Dr. Kalmadi Shamarao High School (KSH), Pune.
Survey No. 36/1+8+9, 38/A, City Survey No. 139 Part, 140,
Plot No. 5 to 9/1A, GM Shetty Educational Complex,
Ganeshnagar, Erandwane, Pune : 411038.

I certify that I have inspected the building of the Dr. Kalmadi Shamarao High School (KSH) at Survey No. 36/1+8+9, 38/A, City Survey No. 139 Part, 140, Plot No. 5 to 9/1A, GM Shetty Educational Complex, Ganeshnagar, Erandwane, Pune : 411038., occupied by Kannada Sangha, the plans of which have been approved by the Pune Municipal Corporation, vide their letter No. CC / 3065 / 12, dated 04.01.2013.

I have done the Structural Audit based on the visual inspection of the accessible parts / areas of the building. Based on the visual observations, visual symptoms & manifestations shown by the structure and the data collected from site, I am of the opinion that the said structure / building is structurally sound and that its stability will not be endangered by its use as a School Building for which structure / building is intended. A detail Structural Audit report covering details about structure, site observations along with photographic survey is attached with this certificate.

I hereby certify that Dr. Kalmadi Shamarao High School (KSH), is found safe structurally for the purpose of utility of building.

Signature of Structural Engineer :

Name of Structural Engineer :  Sunil Mutualik. Chartered Engineer.

License Number Structural Engineer : L. No. 46 – A, (PMC), FIE (No. F-1240265)

Address of Structural Engineer : 1349/1350, Shukrawar Peth,
Arthshilp, 3rd floor, Bajirao road,
Above Hotel Ganaraj, Pune : 411 002.
Ph. No.: (O) 24476705, 24488712.
E – mail : sunil.mutalik@gmail.com

Date : 24.01.2026.

